

Drinking Water Quality Regulator for Scotland

Incident Assessment

Kirbister WTW Distribution (Markstone) Iron Failure 24 April 2010

DWQR Inspector: John Littlejohn

Summary of Incident

This incident arose because after an initial failure of the regulatory 200ug/l iron standard at a property in Kirbister WTW distribution, water quality had not been restored to the required standard within two months.

DWQR Assessment of Cause of Incident

The properties concerned are served by an old cast iron main and Scottish Water instigated a programme of flushing and sampling after the initial failure on 24th April 2010. In spite of this, iron concentrations have not returned consistently to within the regulatory limit.

DWQR Assessment of Actions Taken by Scottish Water

Scottish water took appropriate action to investigate the incident and has a capital project planned to re-line the main in question.