d	Technical Inspection of Scottish Water Treat	ment W	orks	
Turriff WTW, Aberdeenshire 27 April 2012				
-	DWQR Staff PresentMatt Bower, Sue Petch, Bill ByersScottish Water Staff Present (& Titles)Jim Young (Senior Op), Craig Christie, Derek Ogilvie, Finlay Donaldson, Jackie Foster, Paul Hampton (part)			
Summary of Inspection				
Overall Summary				
Turriff is a medium sized water teatment works supplying the North Eastern areas of Aberdeenshire. The works is primarily supplied by abstraction of water from the River Deveron but it is also augmented by the Delgaty Borehole. The intakes were not visited in this audit but the raw water storage reservoir at Woodside and the works itself, are generally well maintained and staff have a good awareness of the operational requirements of the works. The borehole supply has generally fed directly to the filtered water channel in the works but with a significant history of <i>Cryptosporidium</i> events and no monitoring facility on the supply, consideration should be given to delivering this supply into the raw water storage reservoir on a permanent basis.				
	Number of Findings:	10		
0 I'	ty of Water Produced	Score (out of 6) Good	
Turriff produces a good quality water although it has experienced a number of non compliance events in the past year. During this audit the appearance of the water through the various stages was good and monitoring data gave no cause for concern.				
Robu	stness of Treatment Asset	4	Good	
	The treatment processes are appropriate to the raw water from the reservoir and although some aspects of t are currently operating well.	he works an	e in need of attention, they	
Opera	ational Practices	4	Good	
	Whilst there was excellent demonstration of operator competency in some areas, DWQR was unable to gain opersonnel that there was thorough understanding of processes and systems across the team. The necessary out at this works and there is a very good level of attention to record keeping of instrument calibration and n	y checks and	tests are being carried	
Maint	tenance of Asset	4	Good	
	Key maintenance tasks appear to be being undertaken and specialist maintenance contracts are in place for or confusion of old and current labelling of service visits to various pieces of plant and equipment which needs t	•		
Safeg	uards and Procedures	3	Adequate	
	Treatment processes had appropriate alarms in place although some monitors were awaiting repair/replacem provide effective response to problems.	ent. Procec	lures have been shown to	
Wate	r Safety Plan Development and Implementation	5	Very good	
	The WSP recognises an extensive range of risks as would be expected in this type of catchment and these fe Scottish Water has reviewed the various aspects of the treatment process at Turriff and developed an Action observations made in this audit. This needs to feed into the review of the WSP, which is imminent.			