

Technical Inspection of Scottish Water Distribution System

Inverness Regulation Zone, North Region

Aug-22

DWQR Staff Present Moira Malcolm

Scottish Water Staff Present Nick Stewart, Claire Millar

Summary of Inspection

Overall Summary

Two distribution activities audited and examined: a PRV maintenance and a DSR maintenance and repair; undertaken by different contractors. Both were being conducted as a routine activity - no particular quality issues prompted these activities. Both contractors exhibited excellent practices throughout.

Number of Findings:

0