

Assynt Regulation Zone, North Region

Jul-19

DWQR Staff Present

Moira Malcolm

Scottish Water Staff Present

David Hill, Brian Waddell, Reece Porter

Summary of Inspection

Overall Summary

Lead communications pipe replacement observed, using T-Vac. However time and operational needs dictated that no excavation or renewal work were actively observed. Staff were professional and demonstrated good levels of knowledge and practice throughout.

Number of Findings: 1

Quality of Water

No data observed.

Asset Robustness

Assets observed were good, with replacement junction compliant.

Operational Practices

Staff demonstrated an excellent knowledge of the job at hand and the wider hygiene considerations. Van very well organised and appropriately equipped.

Management of Risk

Staff demonstrated good risk management procedures.

Recording Information

Not audited

Water Safety Plan

Not audited