

Balmore Carron Valley RSZ & Balmore C5 North RSZ Contractor-led trunk main conditioning activity 22nd October 2025

The purpose of this audit was to observe contractor-led trunk main conditioning activities following incident 15845. DWQR were satisfied that appropriate measures had clearly been taken to address known risks within this area prior and during the activity.

A tank clean was also observed on the same day. No significant issues with the activity were noted.

DWQR identified four findings. Proposed interventions to address DWQR's findings, along with completion dates and any interim mitigations that will be put in place have been agreed with Scottish Water.

DWQR will monitor completion of agreed interventions, and may request evidence of completion or re-visit the site.